
# 14 DEC 05 (5th Response)



Forecast was for NW part of Area


Hard Freeze <= 00 F/ -18 C.</p>

Wind Chill <= -20 F/ -29 C.
Winter Storm Watch 2" Snow or Freezing Precip & Wind >= 30 Knots or Wind Chill < -20 F/ -29 C.

Weather Advisory Received 131209I Dec 05, 18-hours & 21-minutes prior to snowfall.

Cp Humphreys received 2-inches of snow accumulation between

## **Melting Materials**



## **Barracks (Hiegins HWY)**




# Oflahavan Loop & Hiegins HWY



- From 2030 14 DEC to 0430 15 DEC Cp Humphreys, B&G crews removed snow from the Airfield, Priority 1 roads, & CPX road.
- Self-Help store opened at 0620 issued snow shovels & 100
   Ibs. of Calcium.

### Freedom Rd.



• 3,000 lbs. of Urea was used on the Airfield.

### **Soldier's Park**



• Three Graders, (1) Scoop Loader, (1) each urea/calcium Spreader Trucks conducted snow removal operations.


### Freedom Rd. & Mac Arthur Rd.



#### **Freedom Field**



## 18 DEC 05 (6th Response)



Forecast was for NW part of Area

**→** Hard Freeze <= 00 F/ -18 C.

Wind Chill <= -20 F/ -29 C.
Winter Storm Watch 2" Snow
or Freezing Precip & Wind >= 30
Knots or Wind Chill < -20 F/ -29
C.

Weather Advisory Received 180944I Dec 05, 1-hour & 16-minutes prior to snowfall.

Cp Humphreys received 2-inches of snow accumulation between

#### Freedom Rd.




- From 1100 to 2300 18 DEC Cp Humphreys, B&G crews removed snow from the Airfield, Priority 1 & 2 roads, & CPX road.
- Self-Help store was opened from 1500-1800-hrs, issued snow shovels, 300 lbs. of Calcium & 50 lbs of Urea.

**το νec 05** 

#### Freedom Rd.



 Three Graders, (1) Scoop Loader, (1) Bobcat, (1) Backhoe, (1) Dump Truck, (1) each urea/calcium Spreader Trucks conducted snow removal operations.



- 5,000 lbs. of Calcium Chloride was used on Cp Humphreys road network.
- 17,000 lbs. of Urea was used on the Airfield.
- B & G has requested an additional 50,000 lbs of Urea.







# **Anjung-Ri**



#### **Beacon Hill**



- Monday, 19 Dec follow on work consisted of road clearing, additional airfield clearing and snow pile removal.
- Problems with frozen fuel lines on the airfield sweeper persist. A job order will be submitted to run power to the sweeper, so that engine heaters can be utilized. Water pump on the urea spreader truck is leaking. Two worn out grader blades were replaced at the end of operations.
- Trucks have been re-loaded, B&G crews prepared for next response.

